



Release Notes

FTH-9000 ONMSi Mode

V23.54 – 9 February 2023

Enhancements:

- EPT 9917 – DTSS sensing module management.

Bugs Fixing:

- EPT 9998 - FTH could be unreachable from ONMSi after 10 days period
- EPT 9990 - Wrong budget when modifying test with SmartAcq.
- EPT 9969 - OTU rebooting with monitoring test and sliding reference.
- EPT 9968 - Reboot after Fiber_Optic application abnormal termination could fail.
- EPT 9915 - Missing HardwareSetId in C-HR module EEPROM
- EPT 9806 - Monitoring cycle stops when a DTSS measurement is aborted.
- EPT 9162 – End Of Fiber was not always correctly located by the automatic Measurement

